


Release Notes

Intel® Wireless Bluetooth® 21.20.0



Package Version and Supported Operating Systems	21.20.0 for: Microsoft Windows® 10 Microsoft Windows® 8.1 Microsoft Windows® 7
---	---

Supported Products and Driver Versions

Intel® Wireless Adapter	Windows® 10	Windows® 8.1	Windows® 7
Intel® Wi-Fi 6 AX201	21.20.0.4 ¹	N/A	N/A
Intel® Wi-Fi 6 AX200			
Intel® Wireless-AC 9560 ¹			
Intel® Wireless-AC 9462 ¹			
Intel® Wireless-AC 9461 ¹			
Intel® Wireless-AC 9260 ¹	20.100.6.2	20.92.4.2 ¹	20.90.6.3
Intel® Dual Band Wireless-AC 8265			
Intel® Dual Band Wireless-AC 8260			
Intel® Dual Band Wireless-AC 3168	20.100.6.2	20.92.4.2	20.90.6.3
Intel® Dual Band Wireless-AC 3165		20.91.4.2	
Intel® Wireless 7265 Family			

¹64 Bit only

Key Issues Fixed and Changes on package version 21.20.0

Description of Key Issue	OS
Bluetooth device can get Yellow Bang in Device Manager after more than 10 hours in sleep state.	Windows 10®
After a long duration of a voice call over a Bluetooth headset, the other party may be unable to hear the voice.	Windows 10®
Error message "Bluetooth file transfer not complete" can be shown after Bluetooth OPP file transfer attempt.	Windows 10®
Skype voice may drop when Bluetooth LE mouse is connected to PC along with Bluetooth headphone.	Windows 10®
Bluetooth device connection lost in rare occasions after resuming from Sleep.	Windows 10®
AirPods may suddenly disconnect after several minutes of Hand Free playback.	Windows 10®
General stability improvements and optimizations.	All

Note: Key issues fixed in the OS indicated in the table above.



Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

© February 2018 Intel Corporation.

